




FIG. 1




FIG. 2




FIG. 3A




FIG. 3B




FIG. 3C




FIG. 4A




FIG. 4B




FIG. 4C




FIG. 4D




FIG. 4E




FIG. 4F




FIG. 5A




FIG. 5B




FIG. 6A




FIG. 6B

10/23




FIG. 6C

11/23




FIG. 6D

12/23




FIG. 6E




FIG. 6F

14/23




FIG. 6G




FIG. 7C

FIG. 7B

FIG. 7A




FIG. 8A




FIG. 8B





FIG. 9






FIG. 10B

Effective Lever Arms




FIG. 11A




FIG. 11B




FIG. 11C

